

U.S. Department
of Transportation

United States
Coast Guard



LOCAL NOTICE TO MARINERS

COASTAL WATERS FROM EASTPORT, MAINE TO SHREWSBURY, NEW JERSEY

WEEKLY SUPPLEMENT

OO INTERNET ADDRESS OO

HTTP://www.navcen.uscg.mil

OR

FTP://ftp.navcen.uscg.mil

Weekly supplemental editions contain new information only available following the monthly edition. NOTE: Chart corrections and Light List changes appear only once each. A complete listing of current discrepancies and temporary changes appear in the monthly issue, LNM 27/00. Subscription to this weekly publication is free. If you have questions about the LNM or wish to be on the mailing list, contact:

COMMANDER, FIRST COAST GUARD DISTRICT (oan)

408 Atlantic Avenue, Boston, Massachusetts 02110-3350

Telephone (Day): 1-800-848-3942. To order LNM: Ext. 8335 (After 4:30 p.m. Ext. 7722)

24 Hour FAX: (617) 223-8073

Coast Guard's Customer Infoline (8:00 a.m. - 4:00 p.m.): 1-800-368-5647.

Hearing impaired (TDD) 1-800 689-0816

All bearings are in degrees TRUE - All times are in Local Time unless otherwise noted.

NOTE: A vertical line in the RIGHT MARGIN of sections I, V, VI, VII indicates new information.

BROADCAST NOTICE TO MARINERS

The following Broadcast Notice to Mariners (BNM's) have been issued since last week:

First District	CG1- 0258	to	0264
Group Boston	BOS- 0087	to	0090
Group Long Island Sound	LIS- 0112	to	0120
Group Moriches	MOR- 0093	to	0093
Group New York	NEW- 0192	to	0198
Group Portland	POR- 0048	to	0050
Group Southwest Harbor	SWH- 0047	to	0049
Group Woods Hole	WHO- 0136	to	0145

Light List Reference: ATLANTIC COAST, VOLUME 1, COMDTPUB P16502.1, 1999 Edition

I SPECIAL NOTICES This section contains information of Special concern to the Mariner.

NONE THIS WEEK

II DISCREPANCIES This section lists all discrepancies to Aids to Navigation reported and corrected since the last published list. A discrepancy is a change in the status of an aid to navigation that differs from what is published and or charted.

DISCREPANCIES (since last week)

LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
00000	SAQUATUCKET HBR TEMP BY 3	UNRELIABLE DUE TO DREDGING	13229	WHO-0140-00	30/00
40	HALFWAY RK LT	LT DIM	13003	CG1-0261-00	30/00
1785	PROSPECT HBR PT LT	LT EXT	13260	SWH-0049-00	30/00

10580	WHITE ROCKS LT 7	LT EXT	13275	BOS-0090-00	30/00
13185	BILLINGSGATE LHB 5	FS INOP	13250	WHO-0143-00	30/00
13565	POLLOCK RIP CH LBB 10	LT EXT	13244	WHO-0145-00	30/00
13600	GREAT ROUND SHL CH LB 3	LT IMCH	13244	WHO-0137-00	30/00
13700	NANTUCKET SND LWB NS	LT EXT	13241	WHO-0144-00	30/00
13880	STAGE HBR BY 2B	OFF STA	13229	WHO-0141-00	30/00
20000	CATUMB ROCKS BY 2	MISSING	13214	LIS-0112-00	30/00
23175	CONNECTICUT RIV BY 104	MISSING	12377	LIS-0119-00	30/00
24125	SANDY PT BKW LT	DBN IMCH	12372	LIS-0115-00	30/00
34240	ROCKAWAY IN LB 9	LT EXT	12402	NEW-0196-00	30/00

DISCREPANCIES CORRECTED

LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
45	PORTLAND LHB P	WATCHING PROPERLY	13003	CG1-0255-00	29/00
410	BOSTON LHB B	WATCHING PROPERLY	13270	CG1-0253-00	29/00
440	MINOTS LDG LT	WATCHING PROPERLY	13270	BOS-0087-00	30/00
1560	PLEASANT RIV BY 12	WATCHING PROPERLY	13324	SWH-0047-00	30/00
2700	BURNT COAT HBR LT	WATCHING PROPERLY	13313	SWH-0048-00	30/00
5145	PEMAQUID PT LT	WATCHING PROPERLY	13006	CG1-0185-00	23/00
5145	PEMAQUID PT LT	WATCHING PROPERLY	13301	CG1-0185-00	23/00
5885	COWSEAGAN NARROWS BY 17	WATCHING PROPERLY	13293	POR-0045-00	29/00
6375	UPPER KENNEBEC RIV CH BY 54	WATCHING PROPERLY	13298	POR-0050-00	30/00
6380	UPPER KENNEBEC RIV CH BY 55	WATCHING PROPERLY	13298	POR-0050-00	30/00
7480	PORTLAND LHB P	WATCHING PROPERLY	13290	CG1-0255-00	29/00
8995	MERRIMACK RIV ENT LBB 2	WATCHING PROPERLY	13282	BOS-0088-00	30/00
11320	NEPONSET RIV BY 13	WATCHING PROPERLY	13270	BOS-0089-00	30/00
15350	MUSKEGET CH LWB MC	WATCHING PROPERLY	13237	WHO-0128-00	28/00
15580	TARPAULIN COVE LT	WATCHING PROPERLY	13233	WHO-0139-00	30/00
16315	CUTTYHUNK E ENT LBB CH	WATCHING PROPERLY	13230	WHO-0142-00	30/00
19475	BLOCK IS N REEF LBB 1BI	RELIGHTED	13218	WHO-0138-00	30/00
20155	SEAFLOWER REEF LT	WATCHING PROPERLY	13214	LIS-0111-00	29/00
21055	SILVER EEL POND ENT LBB 2	WATCHING PROPERLY	13214	LIS-0116-00	30/00
23305	CONNECTICUT RIV BY 136	WATCHING PROPERLY	12375	LIS-0113-00	30/00
23925	PINE ORCHARD APP LB 8	WATCHING PROPERLY	12373	LIS-0114-00	30/00
24640	BRIDGEPORT HBR CH LB 19	WATCHING PROPERLY	12369	LIS-0117-00	30/00
28180	SHELTER IS SND N CH LB 12	WATCHING PROPERLY	12358	MOR-0093-00	30/00
34235	ROCKAWAY IN LBB 8	WATCHING PROPERLY	12402	NEW-0195-00	30/00
34380	SHEEPSHEAD BAY BY 18	WATCHING PROPERLY	12350	NEW-0193-00	30/00
34885	AMBROSE CH LBB 14	WATCHING PROPERLY	12402	NEW-0192-00	30/00
35195	SOUTHWEST SPIT JCT LGB SP	WATCHING PROPERLY	12401	NEW-0194-00	30/00
35800	SHREWSBURY RIV CH BY 12	WATCHING PROPERLY	12324	NEW-0197-00	30/00
36035	NAVESINK RIV CH LB 14	WATCHING PROPERLY	12324	NEW-0198-00	30/00

DISCREPANCIES (PRIVATE AIDS)

LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
NONE THIS WEEK					

DISCREPANCIES (PRIVATE AIDS) CORRECTED

LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
NONE THIS WEEK					

III TEMPORARY CHANGES - TEMPORARY CHANGES CORRECTED This section contains temporary changes and corrections to Aids to Navigation for the current week. When aids are temporarily relocated for dredging, a temporary correction shall be listed in Section IV giving the new position.

TEMPORARY CHANGES

LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
NONE THIS WEEK					

TEMPORARY CHANGES CORRECTED

LLNR	Name of Aid	Status	Chart Affected	BNM Ref.	LNM Ref.
NONE THIS WEEK					

IV CHART CORRECTIONS

This section contains corrections to federal and private maintained Aids to Navigation, as well as NOS corrections.

This section contains corrective actions affecting chart(s). Corrections appear numerically by chart number, and pertain to that chart only. The mariner must decide which Chart(s) to correct. The following example explains the individual elements of a typical chart correction.

Chart Number	Chart Edition	Edition Date	Last Local Notice to Mariners	Horizontal Datum Reference	Source of Correction	Current Local Notice to Mariners
↓	↓	↓	↓	↓	↓	↓
12327	91 st Ed.	04/19/97	LAST LNM 26/97	NAD 83	(CG1)	27/97
(TEMP) NY-NJ-NEW YORK HARBOR - RARITAN RIVER						
Add	National Dock Channel Buoy 3, green can					40°41'09.0"N 074°02'48.1"W
↑	↑					↑
Corrective Action	Object of corrective Action					Position (Degrees, minutes, seconds and tenths)

The letter (M) immediately following the chart number indicates that the correction should be applied to the Metric side of the chart only. (Temp) Indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles (NM).

12327	93rd ed. 01/15/2000	LAST LNM : 30/00	NAD 83		30/00
	NY - NJ - NEW YORK HARBOR - RARITAN BAY				CGD01
Change	Gerristen Inlet Buoy 2 to Gerristen Inlet Lighted Buoy 2, Fl R 4s, Red				40-34-13.969N 073-55-03.203W
	(Supersedes LNM 07/00)				
	Kill Van Kull Channel Lighted Buoy 13 from 40-38-30.187N 074-08-28.840W to				40-38-31.094N 074-08-29.467W
12333	31th ed. 06/17/2000	LAST LNM : 30/00	NAD 83		30/00
	NY - NJ - KILL VAN KULL AND NORTHERN PART OF ARTHUR KILL				CGD01
Relocate	Kill Van Kull Channel Lighted Buoy 13 from 40-38-30.187N 074-08-28.840W to				40-38-31.094N 074-08-29.467W
12352	28th ed. 05/06/2000	LAST LNM : 30/00	NAD 83		30/00
(Temp)	SHINNECOCK BAY TO EAST ROCKAWAY INLET				CGD01
Change	State Boat Channel Light 5 to State Boast Channel Buoy 5, Green can (Page F & G)				40-36-53.041N 073-29-55.314W
13003	44th ed. 10/09/1999	LAST LNM : 30/00	NAD 83		30/00
	CAPE SABLE TO CAPE HATTERAS				CGD01
Change	Libbey Island Light to 18 NM				44-34-05.985N 067-22-02.555W
13006	29th ed. 03/22/1997	LAST LNM : 30/00	NAD 83		30/00
	WEST QUODDY HEAD TO NEW YORK (LORAN-C)				CGD01
Change	Libbey Island Light to 18 NM				44-34-05.985N 067-22-02.555W
13260	37th ed. 07/03/1999	LAST LNM : 30/00	NAD 83		30/00
	BAY OF FUNDY TO CAPE COD				CGD01
Change	Libbey Island Light to 18 NM				44-34-05.985N 067-22-02.555W
13293	32nd ed. 04/22/1995	LAST LNM : 30/00	NAD 83		30/00
	DAMARISCOTTA, SHEEPSHOT AND KENNEBEC RIVERS				CGD01
Relocate	Boothbay Harbor Lighted Buoy 9 from 43-50-46.597N 069-37-41.165W to				43-50-47.755N 069-37-44.759W
13296	24th ed. 07/11/1998	LAST LNM : 30/00	NAD 83		30/00
	BOOTHBAY HARBOR TO BATH, INCLUDING KENNEBEC RIVER				CGD01
Relocate	Boothbay Harbor Lighted Buoy 9 from 43-50-46.597N 069-37-41.165W to				43-50-47.755N 069-37-44.759W
13325	14th ed. 11/04/1995	LAST LNM : 30/00	NAD 83		30/00
	ME-QUODDY NARROWS TO PETIT MANAN ISLAND				CGD01
Change	Libbey Island Light to 18 NM				44-34-05.985N 067-22-02.555W
13326	12th ed. 03/20/1993	LAST LNM : 30/00	NAD 83		30/00
	MACHIAS BAY TO TIBBET NARROWS				CGD01
Change	Libbey Island Light to 18 NM				44-34-05.985N 067-22-02.555W

V ADVANCE NOTICES This section contains advance notice of approved projects or upcoming temporary changes such as dredging, etc. Mariners are advised to use caution while transiting these areas.

SUMMARY OF ADVANCED APPROVED PROJECTS		
WATERWAY	Project Date	Ref. LNM
NY/SHELTER ISLAND SOUND	15 SEPT 2000	28/00

CT – NEW LONDON HARBOR - The Coast Guard will be making the following change to Aids to Navigation to facilitate navigation through New London Harbor on or about **11 AUG 00**:

Add New London Harbor Channel Directional LT (LLNR 21948), Occ R 4s, centered on 174.5T and showing for 1.5 degrees to either side in PA 41-21-46.3N, 072-05-16.0W
Chart(s): 13212, 13213, 12372 LNM 44/99 (CGD1).

MA – MERRIMACK RIVER - The Coast Guard will be making the following change to Aids to Navigation to facilitate navigation in the Merrimack River on or about **18 August 00**:

Change Merrimack River North Jetty Light 4 (LLNR 9006) nominal range to 3NM.
Chart(s): 13282, 13278, 13274 LNM 30/00 (CGD1).

VI PROPOSED CHANGES

This section contains notice of non approved, proposed projects open for comment. SPECIAL NOTE: Mariners are requested to respond in writing to: Commander, First Coast Guard District (oan), 408 Atlantic Avenue, Boston, MA 02110-3350, unless otherwise noted.

PROPOSED WATERWAY PROJECTS OPEN FOR PUBLIC COMMENT

WATERWAY	Closing	Docket No.	Ref. LNM
NY/BLOCK ISLAND SOUND	25 Aug 2000	N/A	27/00
ME/MUSCONGUS BAY	31 Aug 2000	N/A	30/00
ME/SOMES SOUND APPROACH	1 Sept 2000	N/A	19/00
NY/NJ	1 Sept 2000	N/A	26/00
NY/KILL VAN KULL	30 Sept 2000	01-00-10	14/00
NY/JAMAICA BAY/ROCKAWAY INLT	30 Sept 2000	N/A	28/00

NONE THIS WEEK

VII GENERAL

This section contains information of general concern to the mariner. Mariners are advised to use caution while transiting these areas.

SUMMARY OF EFFECTIVE DREDGING/CONSTRUCTION OPERATIONS

The following is a listing of marine construction and dredging projects still in effect in the First District. All mariners are advised to use caution in these areas. The LNM REF column refers to the LNM in which the article first appears and where detailed information may be obtained. The dates listed for completion are tentative. An asterisk in the left margin marks new information.

LOCATION	SUBJECT	COMPLETION DATE	LNM REF
MA/CAPE COD CANAL	Entrance Breakwater Repairs	31 July 2000	21/00
NJ/RAHWAY RIVER	Barge loading/unloading	31 July 2000	21/00
NY/BROOKLYN	Dredging	11 August 2000	26/00
MA/BOSTON HARBOR	Caged mussel study	31 August 2000	28/00
NY/NJ/ KILL VAN KULL	Disposal operations	September 2000	35/99
MA/GEORGES BANK	Construction	31 October 2000	25/00
NJ/PORT ELIZABETH	Dredging	24 November 2000	25/00
NY/EAST RIVER	Bulkhead reconstruction	February 2001	16/00
NY/KILL VAN KULL	Dredging	March 2001	11/00
NY/NEW YORK HARBOR	Dredging/Hydrographic Svcs	March 2001	23/00
NY/HOWARD BEACH/BEACH			
CHANNEL/BROAD CHANNEL	Bridge Construction	December 2002	14/00
US/SEACOAST	Cable Laying	until further notice	23/00

NY-SHINNECOCK BAY TO EAST ROCKAWAY INLET - Severe shoaling has been reported in Shinnecock Bay Channel approximately 100 yds to the west of Shinnecock Bay Channel Buoy 15 (LLNR 30760). This shoaling extends across the width of the channel and has an approximate maximum depth of 2.9ft at high tide. All mariners are advised to use extreme caution in the area.
Chart(s) 12300 LNM 29/00 (CGD1)

NY – HUDSON RIVER – Dredging is being done east of the Hudson River, just below the Port of Albany at the National Gypsum loading dock until on or about 24 August, 2000. There will be pipeline. floating and submerged, going from the dredge to the containment area which will be marked with red marker balls and flashing amber lights.
Chart(s) 12348 LNM 30/00 (CGD1)

BRIDGE SECTION

BRIDGE	TYPE	WATERWAY	NM	SUBJECT	REF/LNM
Summer Street	R	Reserved Channel	0.9	Bridge Construction	26-00
Wentworth	B	Little Harbor	0.8	Bridge Repairs & Painting	23-00
International	F	St John River	232.0	Bridge Repairs	24-00

I-93 Main Line	F	Charles River	0.6	Bridge Construction	18-00
P. J. McArdle	B	Chelsea River	0.3	Bridge Construction	23-00
New Rt 3A	B	North River	1.6	Bridge Construction	29-00
Old Providence Road	F	Palmer River	0.7	Bridge Construction	18-00
New Brightman Street	B	Taunton River	2.1	New Bridge Construction	18-00
Rt 3A	B	Weymouth Fore River	2.8	Bridge Construction	21-00
Mount Hope	F	Mount Hope Bay	0.0	Bridge Rehabilitation	21-00
I-95	F	Piscataqua River	4.5	Bridge Painting	26-00
Tomlinson	B	Quinnipiac River	0.0	Bridge Replacement	21-00
Grand Street	B	Pequonnock River	0.9	Bridge Demolition	21-00
Route 1 (Singing)	F	Patchogue River	0.6	Bridge Rehabilitation	18-00
Manhattan Bridge	F	East River	1.1	Rehabilitation/Vert. Clear. Red.	30-00
Manhattan Bridge	F	East River	1.1	Bridge Inspection	20-00
Triborough	F	East River	7.8	Inspection/Vert. Clear. Reduction	29-00
Throgs Neck	F	East River	15.8	Inspection/Vert. Clear. Reduction	27-00
Route 103	F	Erie Canal	28.8	Bridge Rehabilitation	24-00
Robert Moses Causeway	F	Great South Bay	7.3	Bridge Rehabilitation	25-00
125 th Street	VL	Harlem River	1.3	Bridge Inspection	20-00
Macombs Dam	SW	Harlem River	3.2	Bridge Rehabilitation	30-00
Broadway	VL	Harlem River	6.8	Vert./Horiz. Clear. Reduction	29-00
George Washington	F	Hudson River	11.0	Bridge Rehabilitation	18-00
Tappan Zee	F	Hudson River	27.0	Bridge Rehabilitation	21-00
Bear Mountain	F	Hudson River	46.7	Main Cable Rehabilitation	29-00
Mid-Hudson	F	Hudson River	75.6	Painting/Vert. Clear. Reduction	29-00
Kingston-Rhinecliff	F	Hudson River	94.3	Deck Replacement	20-00
Troy-Menands	F	Hudson River	150.2	Tower Removal	22-00
Marine Parkway	VL	Jamaica Bay	3.0	Vert. Clear. Reduction	30-00
Beach Channel	SW	Jamaica Bay	6.7	Bridge Rehabilitation	25-00
Verrazano	F	New York Harbor	0.0	Inspection/Vert. Clear. Reduction	18-00
Atlantic Beach	B	Reynolds Channel	0.4	Bridge Rehabilitation	25-00
Wantagh State Pkwy	F	Sloop Channel	15.4	Channel Closure	25-00
Outerbridge Crossing	F	Arthur Kill	2.0	Bridge Inspection	24-00
Goethals	F	Arthur Kill	11.5	Sidewalk Repairs	29-00
So Front Street	B	Elizabeth River	0.0	Structural Repairs	23-00
Rt 1 & 9	VL	Hackensack River	1.8	Deck Replacement	24-00
Lower Hack	VL	Hackensack River	3.4	Pinion Shafts Replacement	27-00
Rt 1 & 9	VL	Passaic River	1.8	Deck Replacement	24-00
Route 9	F	Raritan River	2.1	Bridge Replacement	29-00
Route 1	F	Raritan River	11.1	Fiber Optic Conduit Install.	30-00

KEY: F-Fixed SW-Swing R-River C-Canal CK-Creek B-Bascule VL-Vertical Lift
Ch-Channel Hbr-Harbor Th-Thoroughfare NM-Nautical mile.

NY - JAMAICA BAY AND ROCKAWAY INLET - ROCKAWAY INLET - Vertical Clearance Reduction - Rehabilitation of the Marine Parkway Bridge across Jamaica Bay at mile 3.0 is in progress. Scaffoldings are installed under the bridge outside the navigable channel. The scaffoldings reduce vertical clearance no more than two feet. A 40ft by 80ft work barge is operating and moored by the Brooklyn abutment. Mariners are advised to use the main channel and to use extreme caution when transiting the area.
Chart 12350 LNM 30/00 (CGD1)

NY - NEW YORK HARBOR –EAST RIVER –HARLEM RIVER - Proposed Bridge Replacement – The U. S. Coast Guard has received an application for a bridge permit from the New York City Department of Transportation. This application proposes to replace the Third Avenue Bridge across Harlem River, between Manhattan and the Bronx, New York City. A temporary two-lane detour bridge will be constructed just upstream for use during construction. Other work to be performed includes increase in vertical clearance under the Oak Point Link railroad (span 7), submarine cable replacement, and rest pier fender replacement. Comments on this proposal should be forwarded to the office of the Commander (obr), First Coast Guard District, One South Street, Battery Park Building, New York, NY 10004-5073 through August 23, 2000. Copies of Public Notice 1-956, which describes the proposal in details, can be obtained by writing to the above address or by calling (212) 668-7165.
Chart 12342 LNM 30/00 (CGD1)

NY - NEW YORK HARBOR –EAST RIVER –HARLEM RIVER - Bridge Rehabilitation – Rehabilitation of the Macombs Dam Bridge across Harlem River at mile 3.2 is in progress. Contractor has installed protective shielding under the span, reducing the available vertical clearance by one foot. A barge measuring 30 feet X 90 feet will be blocking the Bronx side draw during repairs to the fender truss. Mariners are advised to transit the Manhattan side draw. Repairs on the Bronx side are expected to be complete on or about 26 August 2000. The barge will then shift to the Manhattan side draw to effect repairs which are expected to be complete by 28 September 2000. Mariners are advised to exercise caution and reduce wake when transiting the area.
Chart 12342 LNM 30/00 (CGD1)

NY - HUDSON AND EAST RIVERS - EAST RIVER – Bridge Rehabilitation/Vertical Clearance Reduction – Rehabilitation of the Manhattan Bridge across East River at mile 1.1 is in progress. A 120ft wide work platform will be operating under the bridge beginning from mid-span moving toward the Brooklyn Tower. Vertical clearance under the work platform is reduced by approximately 10ft. The work platform will be marked by 4 red lights at the lower four corners. Mariners are advised to exercise caution when transiting the area.
Chart 12335 LNM30/00 (CGD1)

NJ - RARITAN RIVER - Fiber Optic Conduit Installation - Installation of the fiber optic conduit to the Route 1 Bridge across Raritan River at mile 11.1 is in progress. Barges are operating in the waterway from 7 a.m. to 5 p.m., Monday through Friday until further notice. During work hours, mariners can contact contractor via marine radio on channel 13/16 VHF-FM one hour in advance to move the barges out of the channel. Mariners are advised to exercise caution when transiting the area.
Chart 12332 LNM 30/00 (CGD1)

VIII LIGHT LIST CORRECTIONS

An asterisk *, indicates the column in which a correction has been made or new information added.

(1) No.	(2) Name and location	(3) Position	(4) Characteristic	(5) Ht	(6) Rng	(7) Structure	(8) Remarks
1120	Machias Bay Libby Island Light	44 34.60 67 22.00	Fl (2) W 20s	91	18	Granite conical tower. 42	Light obscured from 208° to 220°. Lighted throughout 24 hours. HORN 1 blast ev 15s (2s bl).
					*		* 30/00

Marine Events

LOCATION	DATE/S	TIME	EVENT/SPONSOR	CHART
NY – Rockaway Beach, 360-yd radius safety zone around 40-34-29N 073-50-00W	08/01	2030-2200	Fireworks Display, National Night Night Out Against Crime	12350
NY - Hudson River between Tarrytown and Beacon, NY	08/05	0900-1700	Hudson Rally Peekskill/ Peekskill Celebration 2000	12343
NY – Lake Champlain, between Westport, NY and Scotch Bonnet	08/05	1100-1500	Westport Challenge Regatta/ Westport Marina	14783
NY – Hudson River, from 79 th Street Boat Basin to Pier 62	08/05	1600-1900	Great Hudson River Swim / Manhattan Island Foundation	12335, 12341
NY – Larchmont, Long Island Sound, 240-yd radius safety zone around 40-54-45N 073-44-55W	08/11 (r/d 08/13)	2120-2250	Fireworks Display / Larchmont Shore Club	12367
VT – Lake Champlain, Point Au Roche State Park	08/12	0900-1000	YTRI Triathlon / Plattsburgh YMCA	14781
VT – Lake Champlain, Northwest Bay	08/12	1600-1700	Antique Boat Parade / Westport Marina	14783